

Trucks and Commercial Vehicles



## **Heavy** \_ Troubleshooting VCM\_IMMOBILIZER

Da CET (Pirillo Luigi)






#### You can not to make the key storage via Teleservice, the procedure does not terminate correctly:


- 1) Be sure you are using the correct keys kit (2 Keys + ide 1+ide2 + pin source+ meccanical code).
  - For this operation can not be used the keys parts.
  - Be careful not to use the keys of range € 3
  - Be careful not to use the keys without transponders (only mechanical)
  - If point 1 has been complied
  - You should read the memory faults in the VCM and check if have present errors:

# WHAT YOU NEED WHEN REPLACING THE VCM ON A VEHICLE WITH IMMOBILIZER











DTC	FMI	DESCRIPTION FAULT	SOLUTION / POSSIBLE CAUSES
B4	02	Impossible Programming The TRANSPONDER keys	Transponder key defective, or you are using a key without transponder
	0B	Impossible Programming The TRANSPONDER keys	Transponder key defective, or you are using a key without transponder
	0C	PING SOURCE different between the two keys	The two keys of the kit must have the same Pin source, but id code is different. This means that the keys have been mixed with those of another kit.
	0D	IDE code is been read 2 time, or is same zero	Ide code of the keys can not be read, verify that you are not using a key without a transponder, then only mechanical
	0E	Exceeded the max number of programmable keys	you are trying to add the keys in a VCM, which has already stored inside 7 Keys
B5	02	Key on out of time	The key was kept on for a long time throughout the procedure of memo key .
	0B	Code IDE kit unknown	Code of KIT IDE differently than the one known and stored by the VCM. Probably you are using a key of another Kit
В6	0C	No communication with ECM	the VCM not receive any feedback from ECM, verify the supply ECM and line can between ECM and VCM
	0D	ECM unknown	ECM with another code Immobilizer inside, different from VCM
	0E	IMMOBILIZER function is not enabled in ECM	Reprogram ECM via Teleservice to enable the immobilizer.
В7	02	ECU VCM PLANT MODE, HAS NOT YET keys stored inside	Make a memory keys in VCM.
	0B	ECM in PLANT MODE, memory keys already completed	The ECM is not yet married to VCM, has not yet stored inside the immobilizer code that sent the VCM. Check line can between VCM and ECM.If you replaced the ECM, make the procedure Recognition of new ECM with Easy.
В8	02	ECU VCM PLANT MODE (no keys stored). Procedure and storage keys active	The VCM can not memory keys inside, try another kit of keys
В9	02	FEEDBACK from TRASPONDER wrong	you using a different transponder key with es x € 3, or interference disturbance from mobile phone.
	07	Hardware error on the antenna	Antenna faulty, not correctly positioned. Check the resistance of the antenna (about 9.9 hom between pin 1 and x1-x1-3 of the VCM.
	0B	Inside error of the ECU	Defective inside of VCM, try replacing
	0C	No feedback from the keys TRASPONDER	Means that the VCM not get any response from the transponder. This could be: keys with faulty transponder / keys already stored on another VCM / Key used without transponder (mechanical)



We have 6 situation where FAILS THE PROCESS FOR PROGRAMMING KEYS:

- 1. CASE: VCM WITH ALREADY 2 KEYS STORED
- 2. CASE: PROBLEMS OF ANTENNA
- 3. CASE: YOU ARE USING THE KEYS PARTS (WRONG KEYS)
- 4. CASE: YOU ARE USING BETWEEN TWO KEYS mixed KIT
- 5. CASE: YOU ARE USING THE KEYS ALREADY STORED ON ANOTHER VCM
- 6. CASE: YOU ARE USING THE KEYS WHITOUT TRASPONDER (MECHANICAL)



#### **PREMISE:**

For cases where you can not successfully complete Storing keys BY Teleservice, it is VERY IMPORTANT TO GO TO CONSULT THE READING FAULT MEMORY OF ECU VCM.

That because, when the procedure for storing keys does not end correctly, the VCM gives us always at least 2 Faults:


- 1 PRESENTE
- 1 INTERMITTENTE

The fault present, will always make refers to the fact that the VCM has not yet get any key (PLANT MODE).

The Intermittent Fault instead, it will be essential to understand why the storage procedure fails.




#### 1 CASE: VCM WITH ALREADY 2 KEYS STORED






#### **2 CASE: PROBLEMS OF ANTENNA**





#### **2 CASE: PROBLEMS OF ANTENNA**



and X1-3 of the VCM.

antenna defective, not correctly positioned or one of the two pins unconnected in VCM X1, CHECK THE RESISTANCE OF ANTENNA (9.9 hom APPROXIMATELY between pin X1-1


The DTC: B9 FMI: 07 shows a hardware problem es:

This fault DTC: B7 FMI: 02 indicates that the VCM is IN THE STATE IN WHICH IT IS NOT 'STILL ABLE TO GET THE STORAGE OF 2 KEYS.



#### **3 CASE: YOU ARE USING THE KEYS PARTS (WRONG KEYS)**


The correct procedure, requires the use of keys with different ide, pin source the same for both keys





#### **3 CASE: YOU ARE USING THE KEYS PARTS (WRONG KEYS)**

In practice, I'm using the wrong keys




The DTC: FMI B4: 0C indicates that PIN THE SOURCE OF THE TWO KEY AND 'DIFFERENT or equal to 0, There is not inside of the keys. In fact we were using parts of the keys (3 keys) that does not have inside source vour PIN

This fault DTC: B7 FMI: 02 indicates that the VCM is IN THE STATE IN WHICH IT IS NOT 'STILL ABLE TO GET THE STORAGE OF 2 KEYS.




#### 4. CASE: YOU ARE USING BETWEEN TWO KEYS mixed KIT

The correct procedure, requires the use of keys with different ide pin and source the same for both keys






#### 4 CASE: YOU ARE USING BETWEEN TWO KEYS mixed KIT



The DTC: FMI B4: 0C indicates that PIN THE SOURCE OF




This fault DTC: B7 FMI: 02 indicates that the VCM is IN THE STATE IN WHICH IT IS NOT 'STILL ABLE TO GET THE STORAGE OF 2 KEYS.




#### **5 CASE: YOU ARE USING THE KEYS ALREADY STORED ON ANOTHER VCM**

The correct procedure, requires the use of keys with different ide pin and source the same for both keys





#### **5 CASE: YOU ARE USING THE KEYS ALREADY STORED ON ANOTHER VCM**






This fault DTC: B7 FMI: 02 indicates that the VCM is IN THE STATE IN WHICH IT IS NOT 'STILL ABLE TO LEARNING THE STORAGE OF 2 KEYS.




#### 6 CASE: YOU ARE USING THE KEYS WHITOUT TRASPONDER (MECHANICAL)

The correct procedure, requires the use of keys with different ide pin and source the same for both keys





#### 6 CASE: YOU ARE USING THE KEYS WHITOUT TRASPONDER (MECHANICAL)





This fault DTC: B7 IMF: 02 indicates that the VCM is IN THE STATE IN WHICH IT IS NOT 'STILL ABLE TO GET THE STORAGE OF 2 KEYS.