




# Installation Kibes Run Time Program






For Kibes Run Time installation, firstly copy the sent file that is named Rt\_03\_28, and paste it to your disc (C:\)







Then press "Run" command in Start menu




Press “Browse” button, select the C:\Rt\_03\_28 and open file




Select 'INSTALL' exe. file and press open button




Press space and write ENG to the end of the command (C:\Rt\_03\_28\INSTALL.BAT) that is shown on screen.




This window is shown on screen




After a few seconds, new window is shown on, select part of C and press enter



[C:\KIBES\_R] is shown on screen. Press enter




Select COM1 and press enter again




```
C:\WINDOWS\system32\cmd.exe  
<c> Copyright SiemensUD0 Automotive AG KIBES Installation  
  
Please remember to reboot your computer.  
Press a key to continue.  
  
<Ctrl-X> quit
```


CONFIG.03 trace Yeni Klasör Rt\_03\_28 CONFIG.04 CONFIG.05 ISFYZQVO.... KIBES\_R




After the installation, the next program that is named DosEnaRt6\_1, must be installed. This program is installed to make Kibes enable for Windows NT, 2000 and XP




Firstly, open DosEnaRt6\_1




Start ksetup.exe




Choose KS\_RT.bat file




And copy it




Then open KIBES\_R file ( C:\KIBES\_R). (Before, we have installed this file at your computer).



Choose KS.bat file



Then substitute KS.bat with delivered KS\_RT.bat



KIBES\_R

Dosya Düzen Görünüm Sık Kullanılanlar Araçlar Yardım

Geri Ara Klasörler

Adres C:\KIBES\_R

Dosya ve Klasör Görevleri

Diğer Yerler

Ayrıntılar

**KS\_RT**  
MS-DOS Toplu İş Dosyası  
Değiştirilme Tarihi: 30 Temmuz  
2001 Pazartesi, 10:51  
Boyut: 279 bayt

 DOC	 GPS	 LCM	 LCO	 MAC	 PP_03_28	 PRE	 PST
 SYS	 TMP	 VK_BIN	 ZED_RUN.ENG	 ZED_RUN.GER	 <b>KS_RT</b>	 KS	 RUNTIME.ENG
 RUNTIME.GER	 MNUOLT.ENG	 MNUOLT.GER	 RUNTIME	 HLPOLT.ENG	 Tür: GER Dosyası Değiştirilme Tarihi: 01.09.1999 08:31 Boyut: 897 bayt	 PLCDEF.GER	 PLCDEF.GER
 MNUPP003.ENG	 MNUPP003.GER	 RUNTIME.LGO	 DFMOLT.GER	 DFMOLT.ENG	 COLDEF.ENG	 COLWHI.ENG	 COLBLA.GER
 MNUPP003.ENG	 MNUPP003.GER	 RUNTIME.LGO	 DFMOLT.GER	 DFMOLT.ENG	 COLDEF.ENG	 COLWHI.ENG	 COLBLA.GER

Tür: MS-DOS Toplu İş Dosyası Değiştirilme Tarihi: 30.07.2001 10:51 Boyut: 279 bayt

279 bayt

Bilgisayarım

Başlat

readme - Not Defteri


DosEnaRt6\_1

adsız - Paint


KIBES\_R

Masaüstü


17:19



Delete old KS.bat file



And rename KS\_RT to KS



Now, Kibes Run Time program will work effectively.