

AURORA AIRLINES
A319 VP-BWL CA1406

OPEN MEETING



AURORA AIRLINE **ATTENDEES:**

- Engineer(Maintenance support):Mr. IvanEyde
- Engineer(Engineering support): Mr. Dmitrii Shirokov

AIRASIA ATTENDEES:

Certifying Staff: Mr. Chi-feng Lin

Manager of Planning Control : Mr. Tsung-Lung Su

Manager of Aircraft engineering : Mr. Jianzhou Lai

Manager Of Aircraft Inspection: Mr. Kevin Chang

Sheet Metal Lead man : Mr. Zongyi Guo

Buyer: Ms. Amel Zeng

Material Coordinator(before aircraft hang in) :Mrs Amy Shen

Material Coordinator(after aircraft hang in) : Ms. Melody Liu

Account Manager of Marketing : Ms. Luisa Hsieh

Production Coordinator (PC): Denny Zhang

Production Coordinator (PC): Ms. Annie Wang

ASO:

AIRCRAFT SERVICE ORDER

ASO NO : ..	CA1406..
DATE : ..	25 JAN 2022..

Aircraft PC Coordinator: PIPC ..

AIRCRAFT MODEL & NO. A319 Aircraft S/N:VP-BWL..		EST INPUT DATE 7 FEB 2022..	PRODUCTION TAT 45 calendar days	CUSTOMER : AURORA Airlines..		
TYPE OF WORK D Check..	AAPN .. P1100043..	SERVICE STARTING DATE 8 FEB 2022..	TOTAL LABOR UNDER FIXED PRICE .. EST TOTAL AIRFRAME TIME DURING INPUT ..	ENGINE POSITION	SERIAL NO.	ESTIMATED
	PROJECT NO : .. AUR003..	ETR TEST FLIGHT ..				
	JOB NO : .. CA1406..	ETR DELIVERY 24 MAR 2022..				

AUR A319 Aircraft #VP-BWL (MSN2243) ↵

I. Basic Work Requirements: ↵

1. Performance D Check..
2. Aircraft Ground Handling ..

(Covers receipt of each aircraft support during production period up to 5 days after the aircraft is ready for delivery. Service includes ramp handling, input inventory, input operational check, engine input & output runs, de-fuel, refuel, preflight preparation and inspection for one-time functional test flight and departure flight and severe weather protection services.)..

3. Landing fee..

Note:..

Definition of Non-routine Correction of Discrepancy (COD) or rectification for C Check is defined as follows:..

Non-routine items less than 25 (twenty-five) man-hours for correction of discrepancy for C Check Inspection items as specified in above price will be absorbed by Air Asia. Any item that requires more than 25 (twenty-five) man-hours during C Check Inspection will be charged as Over and Above on actual consumed basis..

For example:..

If a non-routine item requires 26 (twenty-six) man-hours, only 1 (one) man-hour shall be charged to Aurora's account..

FORM 82500 (MAY 05)

Prepared by: Cindy Wang

Approved by: C.L. Su (MPLC)

ASO:



AIRCRAFT SERVICE ORDER

Job No. : CA1406

CONTINUATION SHEET

AIRCRAFT A319 Aircraft VP-BWL

DATE 25 JAN 2022

II. Over and Above Work:

The following services are not included in the above Basic Work Requirements and will be charged as Over & Above, and authorization from the Customer's on-site Technical Representative(s)'s approval is required.

1. Additional items if required.
2. All material/parts/kits and paints provided by Air Asia.
3. Any component overhaul, repair or bench test.
4. Any repainting work if necessary.
5. Aviation fuel and oil required.
6. Additional test flight if required other than one time test flight.



ASO NO. : ..	CAA031..
DATE : ..	4 JUN 2021..

ASO:

Aircraft PC Coordinator: PIPC ..

AIRCRAFT MODEL & NO. A319 Aircraft VP-BWL..		EST INPUT DATE 7 FEB 2022..	PRODUCTION TAT 45 calendar days	CUSTOMER : AURORA Airlines..		
TYPE OF WORK For painting..	AAPN ..	SERVICE STARTING DATE 8 FEB 2022..	TOTAL LABOR UNDER FIXED PRICE . . EST TOTAL AIRFRAME TIME DURING INPUT . .	ENGINE MODEL :		
	P1100043..			ENGINE POSITION	SERIAL NO.	ESTIMATED
	PROJECT NO : ..	ETR TEST FLIGHT				
	AUR12H..					
	JOB NO : ..	ETR DELIVERY				
	CAA031..	24 MAR 2022..				

AUR A319 Aircraft #VP-BWL MSN 2243 For painting job. Re-paint job will be performed by TCAS..

Sub-Job no.

I. Basic Work: -----W/O LF43020-----P1..

清洗及地面支援 W/O: LF43021 *LF43021*

II. Over and Above Work: -----W/O LF43022-----Y1..

III. Rework-----W/O: Be raised by PC-----RW..

AACL CERTIFYING PERSONNEL:



ROSTER FOR AURORA AIRLINES

Issue Date : 06 Jan., 2021
Revision No.: 5


The following personnel are authorized Licensed Mechanics for Aurora Airlines A319/320 Aircraft C-Check

NAME	TITLE	EMPL. NO.	CERTIFICATE	Stamp	Authorized
YAO, SHAO LIANG	SMLP	360701	FAA A&P 3280446, CCAA 803332	B1 102	Release to Service
LEE, CHUNG-CHUNG	DAM	361791	FAA A&P 3388058, CCAA 802964	B1 111	Release to Service
OU, TE-HSIU	Supervisor	360719	CCAA 803447	B1 100	Release to Service
LIN CHI FENG	Supervisor	349169	CCAA 803854	B2 106	Release to Service
CHANG, JUNG-SEN	Supervisor	341149	CCAA 803736	B2 103	Release to Service
LIN, CHUN-SHENG	SMLC	360793	CCAA 803944	B1 101, B2 101	Release to Service
SHIU, SHENG-JUNG	Supervisor	346719	CCAA 803861	B2 104	Release to Service
WANG, CHUN HWA	Supervisor	351312	CCAA 803892	B2 102	Release to Service
CHU, HO-CHING	SMLA	361577	CCAA 803555	B1 103	Release to Service
CHIU, CHIN-TE	Supervisor	347535	CCAA 803767	B2 105	Release to Service
KUO, TSUNG YI	Supervisor	360743	FAA A&P 3325339, CCAA 803427	S 18	Release to Service

Remark: Release to Service: for maintenance task.

Note: This authorization is effective for 2 years from the date of issue unless rescinded.

Nominated By :


Air Asia Manager Quality Assurance

Approved by :


Aurora Airlines

AACL CERTIFYING PERSONNEL:



ROSTER FOR AURORA AIRLINES

Issue Date : 06 Jan., 2021
Revision No.: 5


The following personnel are authorized Licensed Mechanics for Aurora Airlines A319/320 Aircraft C-Check

NAME	TITLE	EMPL. NO.	CERTIFICATE	Stamp	Authorized
CHEN, HP	Supervisor	353409	CCAA 803428	B1 106	Release to Service
SU, TL	A/MAEQ	361923	CCAA 804513	E 6	Release to Service
CHEN, HP	Supervisor	353409	CCAA 803428	B1 106	Release to Service
CHEN, YUNG CHEN	Supervisor	361593	CCAA 804031	B1 110	Release to Service
LIN, WU CHANG	SMLC	361949	CCAA 803439	B1 105	Release to Service
CHENG, CHIH HUANG	MAMS	361626	CCAA 804288	V 3	Release to Service
HSIEH, PC	Supervisor	348088	CCAA 804511	E 9	Release to Service
FANG, REN ZONG	Supervisor	350059	CCAA 804258	E 3	Release to Service
CHANG, WS	A/Superintendent	352039	CCAA 804493&RM 400432	S 25	Release to Service
YUAN, HK	Supervisor	353425	CCAA 803747	B1 108	Release to Service
LIN, CHI FENG	Supervisor	349169	CCAA 803854	B2 106	Release to Service

Remark: Release to Service: for maintenance task.

Note: This authorization is effective for 2 years from the date of issue unless rescinded.

Nominated By :


Air Asia Manager Quality Assurance

Approved by :


Aurora Airlines

AACL CERTIFYING PERSONNEL:



ROSTER FOR AURORA AIRLINES

Issue Date : 06 Jan., 2021
Revision No.: 5

The following personnel are Certifying Staff for Aurora Airlines A319/320 Aircraft C-Check.

NAME	TITLE	EMPL. NO.	CERTIFICATE	STAMP NO.	Authorized
LEE, CHUNG-CHUNG	DAM	361791	FAA A&P 3388058, CCAA 802964	B1 111	CS/MR
YAO, SHAO LIANG	SMLP	360701	FAA A&P 3280446, CCAA 803332	B1 102	CS/MR
OU, TE-HSIU	Supervisor	360719	CCAA 803447	B1 100	CS/MR
CHANG, YU CHEN	SCAI	361733	CCAA 803463	INSP101	CS/MR
CHU, HO-CHING	SMLA	361577	CCAA 803555	B1 103	CS/MR
LIN, WU CHANG	SMLB	361949	CCAA 803439	B1 105	CS/MR

Remark: MR: Maintenance Release

CS: Certifying Staff

Note: This authorization is effective for 2 years from the date of issue unless rescinded.

Nominated By :

Air Asia Manager Quality Assurance

Approved by :

Aurora Airlines

AACL CERTIFYING PERSONNEL:



ROSTER FOR AURORA AIRLINES

Issue Date : 06 Jan., 2021

Revision No.: 5

Inspector/ RII

NAME	TITLE	EMPL. NO.	CERTIFICATE	STAMP NO.	Authorized
CHEN, CHIN-WAN	Engineer	363028	FAA A&P 3606831, CCAA 803468	INSP 105	Inspector
CHANG, YU CHEN	SCAI	361733	CCAA 803463	INSP 101	Inspector
LIANG, PEI LUN	Sr. Engineer	361858	FAA A&P 3392348, CCAA 803404	QC 169	RII
CHENG, CS	Engineer	352667	CCAA 804473	INSP 102	Inspector
CHANG, HSIN-WEI	M/LMD	353920	FAA A&P 3733452, CCAA 804284	QC 111	RII

Note: This authorization is effective for 2 years from the date of issue unless rescinded.

Nominated By : 
Air Asia Manager Quality Assurance

Approved by : 
Aurora Airlines

AACL CERTIFYING PERSONNEL:



ROSTER FOR AURORA AIRLINES

Issue Date : 06 Jan., 2021

Revision No.: 5

NDT/Borescope Inspector/General & Final Inspection for Chemical Laboratory, Cleaning Shop, and Welding/Plating Shop

NAME	TITLE	EMPL. NO.	CERTIFICATE	STAMP NO.	Authorized
WANG, HSIAO-TING	Leadman	360678	CCAA RM 400012	RI 25, NEI 1, ECI 10, FPI 117, MPI 33, IRI 1 & QC501	NDT
WANG, KAI-HUNG	Engineer	344044	CCAA RM 400217	FPI 122, MPI 34, RI 28, ECI 6 & QC502	NDT
WU, PU-CHIN.	Engineer	350611	CCAA RM 400218	ECI 19, MPI 35, FPI 123 & QC503	NDT
TAI, HUNG-LIN	Sr. Engineer	352972	CCAA 801432	ECI 16, UTI 16, FPI 18, MPI 32, RI 18, BSI 3, IRI 2 & QC504	NDT & BSI
CHIAN, CY	Engineer	354689	ROCSNT NDT	UTI 20, ECI 20, MPI 37, RI 20 & QC 506	NDT
HUANG, HAN-PIAO	L/EPI	337396	CCAA 803917	P 5, BSI 2	BSI
CHANG, C. C	L/M	360686		QC408	Chem. Lab.
CJ, GUO	L/M	342882		WLO11	Welding/LII

Note: This authorization is effective for 2 years from the date of issue unless rescinded.

Nominated By :


Air Asia Manager Quality Assurance

Approved by :


Aurora Airlines

A319 VP-BWL CA1406 WORK SCHEDULE

日期	工作
2/7	1. INPUT TIME 16:40
	1. OPERATION TEST
	2. REMOVE ACCESS PANEL
2/8	3. INSPECTION WORK ITEM
	4. NRC ISSUE
	5. MATERIAL ISSUE
	6. AD/SB ITEM JOBS
	7. 13:00 DEFUEL
	8. LOOSE EQUIPMENT CHECK
2/9	1. HANGER IN
	2. REMOVE CABIN SEAT
	3. POLISH FAIRING
2/10	LANDING GEAR NDI INSP
2/10-12	REMOVE CABIN CARPET&FLOOR
2/11	REMOVE FUEL TANK PANEL
2/12-15	REMOVE CABIN GALLEY
2/14-15	CLEAN WHEEL CABIN
2/14-18	1. REMOVE CABIN FLOOR PANEL
	2. QC INSPECTION FLOOR PANEL
	3. REINSTALL CABIN FLOOR PANEL
	4. INSPECTION WORK ITEM FINISH
2/24-25	1. CABIN WORK COMPLETED(SEAT REINSTALL&CARPET NOT YET)
2/24-26	1. CABIN OVERHEAD BIN REPAINTING
3/1-6	1. TAIL SHELF REMOVE (3/1)
	2. AIRCRAFT REMOVE TO NO. 2 HANGER (3/1)
	3. TCAS AIRCRAFT POLISH (NIGHT)
3/7-14	1. AIRCRAFT PAINTING&PAINTING TROUBLESHOOTING
3/15-19	1. AIRCRAFT REMOVE TO NO. 3 HANGER (FIRST ONE INPUT AREA)
	2. ELE POWER ON
	3. HYD POWER ON
	4. ALL SYSTEM TEST
3/19	1. LANDING GEAR UP/DOWN TEST
3/20-21	1. WEIGHT&BALANCE
	2. REFUEL LEAK TEST
	3. WASHING ENG&IDLE RUN TEST
3/22	1. HIGH POWER RUN
3/23	2. WASHING AIRCRAFT
3/24	3. FERRY FLIGHT

Confirmed cases:

- 1. Is there an upper limit on the purchase of materials (belonging to each quotation / direct purchase below the unit price)?

Confirmed

cases:

2. How to sign off the material quotation list?

Example (Type1)

Example (Type2)

*sign off by mail

*sign off by papper work

HANSEO material list0903.xlsx

大小: 100 KB

最後變更日期: 2021年9月6日星期一

訊息 HANSEO material list0903.xlsx (100 KB)


	A	B	C	D	E	F	G	H	I	J	K	L	M
1	材料日期	MRLNO	S	PARN	KEYWORD	QT	U	Unit price(US)	Total Price	LeadTI	ACTCODE	WorkCsd	CUSTOMER APPROV
2	2021/9/1	42HE21.001	1	369QT	OIL	1	QT	27.43	27.43	7	Quotation	BR-023	APPROVED
3	2021/9/1	42HE21.001	2	MILVNOTE TYPE 2	COMPOUND	1	EA	97.974	97.974	0	Quotation	BR-023	APPROVED
4	2021/9/1	42HE21.001	4	VV-L-800	OIL-GL	1	GL	37.92	37.92	7	Quotation	BR-023	APPROVED
5	2021/9/1	42HE21.001	5	AEROSHELL NO.64	GREASE	1	TU	20.39	20.39	7	Quotation	BR-023	APPROVED
6	2021/9/1	42HE21.001	6	SHC100AV14-4LB	GREASE	1	EA	86.55	86.55	0	Quotation	BR-023	APPROVED
7	2021/9/1	42HE21.001	7	LF83	COMPOUND-00316	1	EA	16.267	16.267	0	Quotation	BR-023	APPROVED
8	2021/9/1	42HE21.001	8	ACF-50	LUBRICANT	1	EA	11.87	11.87	7	Quotation	BR-023	APPROVED
9	2021/9/1	42HE21.001	9	DCM77-3502	GREASE-35 02	1	CN	189.48	189.48	7	Quotation	BR-023	APPROVED
10	2021/9/1	42HE21.001	10	130AA	GREASE-CN	1	CN	13.95	13.95	7	Quotation	BR-023	APPROVED
11	2021/9/1	42HE21.001	11	64-6-5LB	GREASE-6.5LB	1	CN	114.18	114.18	7	Quotation	BR-023	APPROVED
12	2021/9/1	42HE21.001	12	9434	PREVENTER	1	CN	11.316	11.316	0	Quotation	BR-023	APPROVED
13	2021/9/1	42HE21.001	13	SHF93-50L	GEAR OIL	1	EA	315	315	17	Quotation	BR-023	APPROVED
14	2021/9/1	42HE21.001	14	MIL-PRF-10924	GREASE	1	TU	665	665	7	Quotation	BR-023	APPROVED
15	2021/9/1	42HE21.001	15	TR-TYL5000T	COMPOUND	1	QT	30.88	30.88	7	Quotation	BR-023	APPROVED
16	2021/9/1	42HE21.001	16	AEROSHELL NO.12	OIL	1	EA	125.7	125.7	5	Quotation	BR-023	APPROVED
18	2021/9/2	42HE21.002	1	AEROSHELL NO.22	GREASE-37LB	1	LB	17.838	17.838	0	Quotation	BR-023	APPROVED
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
31													
32													
33													
34													
35													
36													
37													
38													
39													
40													
41													
42													
43													
44													








Confirmed

cases:

- 3. NRC sign off format ?


 886119F2007003

AIA ASIA **NONROUTINE WORK CARD** CARD NO. CA1165-001

MODEL BN-2B-	ACFT NO. B-69896	JOB NO. CA1165	SKILL 1020 42110	EST. HRS. 16	HRS. APPROVED. 16	HRS. APPROVED BY  8/13
ATA 53	ZONE	REF. DOCUMENT				
DISCREPANCY	THIRTY ONE PIECES OF FUSELAGE EXTERNAL PANELS HAD SURFACE CORROSION					
AS REMARK						
 			DISCOVERED BY 362921 C. HU	DATE DISCOVERED 2020-07-29		
CORRECTIVE ACTION	① CORROSION REMOVED & TREATED. PER: SRM PC-A-51-00-01-00A-254A-A PC-A-20-10-20-02A-259A-A ② THE MAX CLEAN UP DEPTH IS 0.001" WITHIN ALLOWABLE LIMIT. PER: SRM PC-A-51-10-01-00A-284A-A (PME NO: 00469). DATE DUE: 14 JAN 2021					
DONE BY 17-2-2021 302419			INSP BY 	DATE 2020/08/13		
NOMENCLATURE	OFF-PART NUMBER	OFF-SERIAL NUMBER	ON-PART NUMBER	ON-SERIAL NUMBER	REVIEWED BY 	

FORM 8440300 REV. 1. ORIGINAL-WHITE WORK UNIT-PINK EST. HRS - GREEN

Confirmed cases:

- 4. Is there any log book item?
- 5. Will A319 do compass swing ?
- 6. Do the cabin overhead bin slat need to remove the scratch?

7.ED 00025076 Cockpit Window information

P/N&S/N&FC&FH

STATE OF INSPECTION : _____ SHEET IN ACCORDANCE WITH ISI 00.00.00179

INSPECTION METHOD : DETAILED INSPECTION

INSPECTION INFORMATION		
OPERATOR		
INSPECTION TYPE	<input type="checkbox"/> ON AIRCRAFT	<input type="checkbox"/> IN SHOP
INSPECTION DATE		

WINDSHIELD INFORMATION	
PART NUMBER (PN)	
SERIAL NUMBER (SN)	
FIRST INSTALLATION DATE	
FC	
FH	

GROUP 2 ONLY

FAULT MESSAGE "561000 R WINDSHIELD SENSOR" RECORDED SINCE WINDSHIELD INSTALLATION ON AIRCRAFT?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
APPLICABLE THRESHOLD	<input type="checkbox"/> 4 MONTHS	<input type="checkbox"/> 12 MONTHS	<input type="checkbox"/> 24 MONTHS

GROUPS 1 AND 3 ONLY

VISUAL INSPECTION FOR DELAMINATION AND BUBBLES	<input type="checkbox"/> FINDING	<input type="checkbox"/> NIL FINDING
------------------------------------------------	----------------------------------	--------------------------------------

**THANK
YOU**

AIA ASIA
Company Limited